N	я	m	e	•
⊥ 1	"		•	

**Enrolment No:** 



## UNIVERSITY OF PETROLEUM AND ENERGY STUDIES

Online End Semester Examination, June 2021

**Course: Workshop Practices** 


Program: B. Tech

**Course Code: MEPD1003** 

**Semester: I** Time 03 hrs.

Max. Marks: 100

	SECTION-A: Total 30 marks Each question carries 5 marks				
Vo.	Each question carries 5 marks	CO			
	Identify the hand tools in below images:				
	a b FLAT RATIO C C C C C C C C C C C C C C C C C C C				
	d e	CO			
	a), b), c), d), e)				
	True/False:				
	<ul><li>a) Electric arc welding using DC requires higher potential as compared to AC.</li><li>b) Electric arc welding using DC gives better arc stability as compared to AC.</li></ul>				
	c) Grooving operation is done on a lathe machine to create markings for better grip.	- co			
	d) A core is used to create hollow sections during casting.	-			
	e) For every metal/alloy, recrystallization temperature is above 700 °C.				
	True/False:				
	a) Cold working leads to more internal stresses in the material as compared to hot working				
	b) During cold working, better surface finished is obtained as compared to hot working.	CO			
	<ul><li>c) Hot working is preferrable when large changes in shape are required.</li><li>d) Cold-worked products are generally stronger than hot-worked products.</li></ul>	CO			
	e) Hot working leads to formation of new stress-free grains.				



Q 8	a) Label the various parts (1-8) of lathe machine as shown in the figure below:  Note: Part no. 3 represents a collection of different components lying inside the marked circle.  (8 marks)	CO4
	b) Briefly discuss the role of cross-slide in lathe machine. (2 marks)	
Q 9	a) Identify the following defects in cast products:  (4 marks)  (4 marks)  (6 marks)	CO1
Q 10	Answer the following:  a) The moulding sand must have good refractoriness and permeability. Why are these properties required in a moulding sand?  c) Briefly discuss how hollow sections are created in a cast product. Also mention why chaplets are used in the mould making process. (5 marks)	CO1

Q 11	<ul> <li>a) With the help of a detailed schematic diagram, describe the abrasive jet machining process. (6 marks)</li> <li>b) Mention the various parameters that are used to control the abrasive jet machining process.</li> </ul>	
	(4 marks)	
	SECTION-C	
Q 12	Option A: Electric Arc Welding (EAW)	
	A.i) Draw a schematic diagram to show the setup used for electric arc welding (EAW) process.	
	A.ii) Briefly discuss the MIG (Metal Inert Gas) and TIG (Tungsten Inert Gas) welding processes using schematic diagrams.	
	A.iii) Briefly discuss following defects in welding: a) Overlap and b) Poor-fusion	
	A.iv) Mention the composition of flux used for coating the electrodes in EAW. Also discuss why electrodes are coated with flux.	
	OR	CO2
	Option B: Gas Welding, Brazing & Soldering	
	B.i) List the fuel used in gas welding process. Briefly discuss the role of oxygen in gas welding process.	
	B.ii) Discuss the different types of flames used in gas welding process.	
	B.iii) Discuss the differences between welding, soldering and brazing.	
	B.iv) Briefly discuss following defects in welding: a) Under-cutting, and b) Cracking	