

Analysis & Redesigning of Watermills for Sustainable Development of Rural Areas of Uttarakhand

LIST OF FIGURES

Figure No	Contents
1.1	Traditional Wooden Watermill Installed at Katapathhar
1.2	General Site Layout for a Watermill
2.1	Conventional Watermill System
3.1	Woman Grinding Grains at a Watermill at Chakrata dated 18.06.2008
3.2	Photograph of a watermill taken just below the road head at Pipalkeli, Chamoli dated 22.06.2008
3.3	Traditional runner of a watermill at Ukhimath dated 23.06.2008
3.4	Miller showing his damaged runner of a watermill at Ukhimath dated 23.06.2008
3.5	Open penstock of a watermill at Chakrata dated 18.06.2008
3.6	Damaged Penstock Nozzle at a Watermill at Bhatwari dated 20.06.2008
3.7	Damaged watermill turbine at Tehri dated 16.06.2008
3.8	Breached Channel at a site in Bhimtal dated 28.06.2008
3.9	Trash accumulation at a site in Almora dated 29.06.2008
3.10	Wooden Screen at a site in Almora dated 29.06.2008
4.1	Economic Curve for selection of Penstock Diameter
4.2	Design of Penstock
4.3	Design of Nozzle
4.4	Design of Jet
4.5	Design of Runner Assembly
4.6	Design of Shaft
4.7	Design of bearing plate & Greasing arrangement
4.8	Design of Shisham bush for bearing Cap
4.9	Impact of blade angle
4.10	Design of Jet Diameter

Analysis & Redesigning of Watermills for Sustainable Development of Rural Areas of Uttarakhand

- 4.11 Control of Jet Diameter
- 4.12 Trash Tank and De siltation Tank
- 4.13 Battery Charging arrangement of watermill
- 5.1 Schematic of Improved Watermill Assembly
- 5.2 Head Measurement
- 5.3 Head Measurement using Water filled tube
- 5.4 Head Measurement Using Water Filled Tube (all level)
- 5.5 Head Measurement Using
 - Sprit Level and Wooden Plank
- 5.6 Bucket Method
- 5.7 Float Method
- 5.8 Cross Section of Stream
- 5.9 Rectangular-Notch Weir
- 5.10 Procedure of the replacing the ball
- 5.11 Layout of model Watermill
- 5.12 Forebay Section and Base slab
- 5.13 Tailrace Section
- 5.14 General Arrangement Drawing of Improved Watermill